

PHASE IV DEBRIS REMOVAL SURVEY
Environmental Unit Review

Waterway: Galva Canal - # 7003

NOAA reviewer: Jessica White

Date: 3/21/2008

Checklist of Environmental Factors – Assess the potential for impacts to the following resources/areas and coordinate as necessary:

- ☒ Habitat/environmental sensitivity *Marsh around river - no traffic there to avoid*
- ☒ Threatened/endangered species *No ^{ruts} work that would damage sandy areas.*
- ☐ Cultural/historical resources
- ☐ Oyster habitat
- ☒ State/federal/tribal lands *Call Manchac manager - coordinate with them.*
- ☐ Scenic waterway

Summary and Conclusions of Environmental Review:

Habitat: Waterway is surrounded by intermediate marsh and some forested wetland. Avoid creating ruts in this soft ground by limiting travel to open water.

Biological resources: A rare reptile (#514, turtle) may be present in or around the waterway. Do not disturb shoreline, banks, or sand bars in the area. If sea turtles are seen in the work area they must be avoided.

Cultural/historic: No known resources in waterway.

Oyster habitat: No oyster leases or public areas in this waterway.

State/federal/tribal lands: The waterway is within the Manchac WMA. You must contact the WMA manager to coordinate the operations.

Scenic waterway status: Not a scenic waterway.